Report on Inspections for Application No. B/2013/0232/

Location: Belle Vue La Rue du Val de la Mare,,St. Ouen

Report produced on the 15/02/2022

Date	Туре	Surveyor	Result	Cost
07/05/2013	Notes		Unsatisfactory	0.00
been prod		erations of an existing b	version and new garage. However thouilding, where as two separate certification contacted to expense to expens	
03/07/2013	Notes	s	Satisfactory	0.00
sche	dule 2 for "unkown items". SE <u>R certifica</u> te J004758 for ne		ssociated extension received and ac	knowledged by fax. (see
08/10/2013	Commencement Of Work		Satisfactory	0.00
Notes: Com	mencement Of Work			
09/10/2013	Routine		Satisfactory	0.00
Notes: Rout grou	ine - called after receiving com nd level inside the building whic	mencement notice - de ch is to be converted.	moltion and site clearance work in p	rogress and reducing the
17/10/2013	Routine		Satisfactory	0.00
	rough the existing barn to reac nded that rocker pipes etc will b Drainage		ipe enters and exits the barn Unsatisfactory	0.00
			age area it is beede in chippings but and not to cover up until seen agair	
23/10/2013	`		Satisfactory	0.00
Notes: Drair	nage - clay removed and drains	now surrounded with	small size gravel - ok to continue.	
28/10/2013	Excavation For A Foundati	c	Satisfactory	0.00
and or remo	contractor will blind area as he oved prior to blinding,, contracto	levels through, discuss or mentioned that confi	ge store area, bearing strata to mix of ed with him that if any soft spots are guration of rear wall is to change, ran d prior to any structural concreting be	uncovered they should be
31/10/2013	Foundation Concrete		Satisfactory	0.00
	dation Concrete - underpinning er confirmed taken through full		onditions are firm yellow clay , 3 no so 450mm.	equences done to date ,
01/11/2013	Concrete Oversite		Satisfactory	0.00
	o be used for the new type reta		rsite , bottom mesh in place Z bars o ed out to banks L bars used in pot b	
05/11/2013	Notes		Satisfactory	0.00
05/11/2013 Notes: Note 2 iter Certi	s: SER certificate J005102 for i	revised retaining wall c	Satisfactory onstruction received and acknowledo	

14/11/2013 Damp Proof Course Satisfactory 0.00 Notes: Damp Proof Course garage, - dpc,s laid - flat dpc laid across the slab with a tray laid above, reminded that weep holes shouls be provided for the tray 15/11/2013 Excavation For A Foundation Satisfactory 0.00 Notes: Excavation For A Foundation - the area for the barn extension has been excavated onto mainly firm yellow clay but there are areas of cowbelly The engineer has visited site and asked for the cow belly to be removed (see e mail in info at work) This has still to be done and there is still some softer clay where the new entrance to the existing building has been formed - this also needs removing. Agreed ok for builder to blind providing he does as required as he wants to blind pm whilst the weather is still dry. 18/11/2013 Routine Satisfactory 0.00 Notes: Routine - the area has now been blinded with edge deepenings as shown, steel work now to be set up and aked that the land drain is taken to the soakawayas it is presently has no outfall. 20/11/2013 Drainage Satisfactory 0.00 Notes: Drainage - drain laid for proposed kitchen ok but on opposte wall of what is shown on plan as the kitchen layout is to The external drains are also to change again and now will not be going through the barn but exiting the site alongside the new extension. 21/11/2013 Drainage Satisfactory 0.00 Notes: Drainage - drain laid in the drive area from the garage towards the manhole which takes the runs to the tank Agreed the builder can carry on laying the drain from the same manhole towards the existing house and fill the trench as the trenches are collapsing due to the water around There is plenty of fall available and the bedding chippings are on site. The foul drainage layout to date is similar to what is sshsown for RW 11 - RW 2 and FWM 5 - to the house 22/11/2013 Drainage Satisfactory 0.00 Notes: Drainage - no further drainage work carried out , only the run through the drive to the garage done Builder to leave run to main house until early next year when the tank is in. 25/11/2013 Concrete Oversite Satisfactory 0.00 Notes: Concrete Oversite - the steelwork is in place for the slab and retaining walls All looks ok also on site Friday The Sika agent is also on site as waterproof Sika concrete is being used Battens for water bars are also in place in the upstand. 0.00 26/11/2013 Drainage Satisfactory Notes: Drainage - the drains are being across the field towards the land drain system being laid to fall and bedded in chippings went over land drain system with diagram in part H with the drainlayer, pointed out 1/200 fall and sampling point etc. 28/11/2013 Drainage Satisfactory 0.00 Notes: Drainage - drain across top field almost complete, laid to falls and bedded in chippings ok. work to drainage crossing the road about to start agreed back drop detail and drain below road to be protected with concrete. 04/12/2013 Routine Part Satisfactory 0.00 Notes: Routine - the shuttering and steel for the concrete retaining wall is in place and looks ok but the water bar has gaps where the joints occur. Foreman informed the Sika consultant is comimng to site before the pour and he will speak to him on whether the gaps are acceptable - asked to be kept informed. 04/12/2013 Drainage 0.00 Satisfactory Notes: Drainage - the drains have now been laid through the lower field and builder informed all laid and bedded as seen with the previous drainage. The manhole that is to take the drainage to the land drain system is to be sited in the hedge. No testing to date. 06/12/2013 Drainage Satisfactory 0.00

Notes: Concrete Oversite - most garage steel work in place except for the extending bar F where required.

Notes: Drainage - the land drain system has commend loop 45 degree bends for corners and reminded		m runs to go in , in a
06/12/2013 Routine	Satisfactory	0.00
Notes: Routine - spoken to foreman regarding the water over the gaps at the joints which was then put it		300mm wide strips
19/12/2013 Routine	Part Satisfactory	0.00
Notes: Routine - the walls to extension are up past firs and ok'd generally but the person asked for the be done) - to be confirmed and notes of visit re	tray on the rear wall to be extended through the granit	
20/12/2013 Notes	Unsatisfactory	0.00
Notes: Notes - it has become apparent that the builder) but no one from this department mad who is involved in supervising the wor The dpc;s as they arewill have to remain.	le the visit. The person who gave the advice on the tray	
02/01/2014 Routine	Satisfactory	0.00
Notes: Routine - little change since the last visit , slab	pouted in the converted building , no builders on site.	
13/01/2014 Damp Proof Course	Satisfactory	0.00
Notes: Damp Proof Course - discussed dpc's to the exnew floor is slightly below the outside ground le Reminded that the wall and floor requires seaili		d be used as the
04/02/2014 Roof	Satisfactory	0.00
Notes: Roof - new roofs on to garage and extension (sengineers dwg but pointed out that the joints to The collars have also been put in to the existing	the Tri iso need taping and noggins below the joints ar	
25/02/2014 Routine	Satisfactory	0.00
Notes: Routine - roofs on and part covered to main but vertical dpc at door and windows placed at bac Cavities to be sealed and wall insulation is to be	k of granite and to lap onto frame	agreed 150mm
14/03/2014 Routine	Unsatisfactory	0.00
Notes: Routine - the floor insulation in the dwelling has damaged it needs replacing The cavities have been partly sealed but it can and call office before sealing	s been put down and has been walked on and worked on be seen that the wall ties need cleaning - asked foremand	•
20/03/2014 Routine	Part Satisfactory	0.00
Notes: Routine - the wall ties have been cleaned, ask Noted dampness around the first course of bloo Builder lifted insulation board which showed wa builder informed the floor was flooded when the and the floor and the borads are to be dried price	ck work internally ater on the slab above the dpm e diamond drilling macine was recently used - all board	
09/04/2014 Routine	Part Satisfactory	0.00
Notes: Commencement Of Work - the floors in the dwe insulation had been dried out prior to screeding. The windows on the upper floors are low level (and reminded of moe requirements)		
The foreman is now to discuss with	and owner and decide on how to provide measure	es
29/04/2014 Drainage	Unsatisfactory	0.00
Notes: Drainage - drainage has been laid to the front a Some areas have been bedded in sand - inform Asked builder to notify when chipping bedding it	ned sand is not n acceptable form of bedding and it nee	
		0.00
Notes:		
06/05/2014 Drainage	Satisfactory	0.00

lotes: Drainage - the drain run from the manhole on the corner of the laid - approx 1.5m deep, laid to fall and bedded in chippings existing foundations for when they lay a new pipe across the	, reminded builder of keeping deep	
3/05/2014 Drainage s	Satisfactory	0.00
lotes: Drainage - air test to the internal stack and drainage to the k	itchen from the manhole in the upper	yard - both held ok.
4/06/2014 Routine	Satisfactory	0.00
lotes: Routine - went over the stair with the foreman and the risers exceed 800mm which is acceptable in the BS. Also went over recently laid drainage in the garden of the man		r 2R + G does not
8/06/2014 Routine	Part Satisfactory	0.00
lotes: Routine - met the foreman on site to go over escape window The escape window in the upper bedroom does not open to Removable guarding is also required to the escape windows openings below 800mm which are not escape windows - a r	0.33m2 - horns to be cut off the lowed (both bedrooms) and where the fire	st floor windows have
4/06/2014 Completion	Part Satisfactory	0.00
Iotes: Completion - outstanding 1/ escape window to bedroom to be replaced and made larg 2/maintenance notice etc to be provided for the treatment sy 3/ cylinder blow off to be turned back to wall and type of plas 4/handrail and landing required to external stair 5/ window at bottom of stair to be fixed shut 6/ glass guarding strength to be confirmed 7/ all glass guardings to be completed 8/ electrical notification required	stem	
Note - bars with removable pins have been put where the es aretightened to prevent easy removal by children 9/ guarding to low level opening in bedroom to complete 10 / drainage to test 11/ handrail etc reqd to lower stair in dwelling	cape window is below 800mm but as	sked tha the pins
1/07/2014 Routine	Part Satisfactory	0.00
lotes: Routine - called to check outstanding items - still outstanding 1/ maintenance notice etc to be provided for the treatment sy 2/ glass guarding strength to be confirmed 3/ drainage to test 4/ type of glass to be confirmed in the new casement window 5/ handrail required to lower internal stair	/stem	
2/07/2014 Routine	Part Satisfactory	0.00
lotes: Routine - drainage tested and ok - outstanding 1/ maintenance notice etc to be provided for the treatment sy 2/ glass guarding strength to be confirmed 3/ glass to be changed in the new casement window 4/ handrail required to lower internal stair	/stem	
8/08/2014 Routine	Part Satisfactory	0.00
otes: Routine - called to check on outstanding items - there doesn	't seem to be any further progress - o	comp 1 to go.
8/08/2014 SER Acknowledgement	Satisfactory	0.00
otes: SER Acknowledgement - structural certificate J 00 8793 rece	eived.	
6/09/2014 Completion	Satisfactory	0.00