

[REDACTED]

**From:** [REDACTED]  
**Sent:** 23 June 2021 11:37  
**To:** [REDACTED]  
**Cc:** [REDACTED]  
**Subject:** RE: 8 & 9 Brooklyn Mews

Many thanks for your emails. I have asked the officer who dealt with the job to contact you. Please be aware that we are very busy and short staffed at the moment.

My understanding however is that the roof always sloped this way, [REDACTED]. Surely now that a sealed roofing system has been provided, rather than corrugated as previous, this is now better? Do you have any photos of the junction detail prior to the works?

regards

[REDACTED] | Principal Building Control Surveyor | Building Control

Infrastructure Housing and Environment | Regulation  
PO Box 228 | Jersey | St. Helier | JE4 9SS  
T: +44 (0) 1534 [REDACTED]  
E: [REDACTED]@gov.je  
W: [www.gov.je](http://www.gov.je)



 **Click here to rate our service**

We're committed to giving you the best possible service – every day, everywhere.

**Your Privacy**  
We take great care to protect your data. For information about how we use and store your data, please view our [Privacy Statement](#). Please note, telephone calls may be recorded for monitoring and training purposes.

---

**From:** [REDACTED]  
**Sent:** 23 June 2021 11:30  
**To:** [REDACTED]@gov.je>  
**Cc:** [REDACTED]  
**Subject:** RE: 8 & 9 Brooklyn Mews

Dear [REDACTED],

May I add that the new Structure of the at Brooklyn Mews is inclined, so that the water will run straight into the [REDACTED], which will cause water ingress/damp to [REDACTED], making [REDACTED] inhabitable. The roof should be altered to allow the rain water to run away from [REDACTED]?

Yours Sincerely,

[Redacted]

---

From: [Redacted]  
Sent: 23 June 2021 11:13  
To: [Redacted] @gov.je' [Redacted] @gov.je>  
Cc: [Redacted]  
Subject: 8 & 9 Brooklyn Mews

Dear [Redacted]

Thank you for the courtesy extended to me during my telephone call this morning.

I am worried about the quality of the works at the above property that have been recently completed. My major concern is regarding water ingress [Redacted] as it appears that the temporary Corrugated plastic roofing sheets installed by [Redacted], have been replaced with a permanent structure over the border between [Redacted] and Brooklyn Mews.

From the photo attached the rain water will drain straight into [Redacted], making the [Redacted] [Redacted] with this matter.

Kindly note that [Redacted] [Redacted] Is a member of your team available sometime today or tomorrow to meet with me at [Redacted] to look at the areas that are of concern [Redacted] ?

Many thanks,  
[Redacted]

[Redacted]



This email has been checked for viruses by Avast antivirus software.  
[www.avast.com](http://www.avast.com)